	Ref #	Hits	Search Text	DBs	Time Stamp
1	S1	95318	transmission near3 (speed or rotation$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:01
2	S2	9382	(transmission near2 (input or output or member or compenent)) near3 (speed or rotation$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:02
3	S3	10819	(provid$3 or calculat$3 or determin$3 or detect$3 or sens$3 or obtain$3) near5 (transmission near3 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:03
4	S4	2323	(provid$3 or calculat$3 or determin$3 or detect$3 or sens$3 or obtain$3) near5 ((transmission near2 (input or output or member or component)) near3 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:04
5	S5	279697	(input or output or transmission or engine) near3 speed$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:04
6	S6	25234	(sensor or sens$3) near3 ((input or output or transmission or engine) near2 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:05
7	S7	3671	((input or output or transmission or engine) near3 speed$1) near10 (electric near3 motor$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:06
8	S8	2398	ratio$1 near5 ((transmission or engine) near3 motor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:07
9	S9	409	((engine or transmission or input or output) near3 speed$1) near10 (ratio$1 near5 ((transmission or engine) near3 motor))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:08
10	S10	22063	(select$3 or utiliz$3 or us$3) near3 ((transmission or input or output or member or engine) near2 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:09
11	S11	224	(transmission near3 speed$1) near10 (motor near3 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:10
12	S12	95	(transmission near3 speed$1) near10 ((motor near3 ratio) near5 (motor near3 (speed or rotation$1)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/17 18:10

	Ref #	Hits	Search Text	DBs	Time Stamp
41	S41	95318	transmission near3 (speed or rotation$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
42	S42	9382	(transmission near2 (input or output or member or compenent)) near3 (speed or rotation$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
43	S43	10819	(provid$3 or calculat$3 or determin$3 or detect$3 or sens$3 or obtain$3) near5 (transmission near3 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
44	S44	2323	(provid$3 or calculat$3 or determin$3 or detect$3 or sens$3 or obtain$3) near5 ((transmission near2 (input or output or member or component)) near3 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
45	S45	279697	(input or output or transmission or engine) near3 speed$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
46	S46	25234	(sensor or sens$3) near3 ((input or output or transmission or engine) near2 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
47	S47	3671	((input or output or transmission or engine) near3 speed$1) near10 (electric near3 motor$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
48	S48	2398	ratio$1 near5 ((transmission or engine) near3 motor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
49	S49	409	((engine or transmission or input or output) near3 speed$1) near10 (ratio$1 near5 ((transmission or engine) near3 motor))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
50	S50	22063	(select$3 or utiliz$3 or us$3) near3 ((transmission or input or output or member or engine) near2 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
51	S51	224	(transmission near3 speed$1) near10 (motor near3 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
52	S52	95	(transmission near3 speed$1) near10 ((motor near3 ratio) near5 (motor near3 (speed or rotation$1)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11
53	S53	88481	(hybrid or electric) near2 (vehicle$1 or transmission or powertrain$1 or drivetrain$1 or engine$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:56
54	S54	8784	S41 and S42	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 06:11

	Ref #	Hits	Search Text	DBs	Time Stamp
76	S76	1762	transmission near3 (speed near2 sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:20
77	S77	1573	((input or output) near1 shaft) near3 (speed near2 sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:22
78	S78	759	((speed or rotation) near2 sensor) near3 (speed near2 transmission)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:23
79	S79	915	((speed or rotation) near2 sensor) near3 ((input or output or member) near2 transmission)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:23
80	S80	171552	speed near3 motor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:24
81	S81	5507	((input or output or transmission) near2 speed) near5 (motor near2 speed)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:25
82	S82	165	((input or output or transmission) near2 speed) near10 (((speed or rotation) near2 ratio) near5 (motor near2 speed))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:25
83	S83	2855	(select$3 or switch$3) near3 (transmission near2 speed$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:26
84	S84	3352	(fault$2 or error$1 or abnormal$4 or diagno$5 or analy$4 or monitor$3) near5 ((transmission or speed) near2 sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:28
85	S85	47	(fault$2 or error$1 or abnormal$4 or diagno$5 or analy$4 or monitor$3) near5 ((transmission near2 speed) near3 sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:29
86	S86	7928	((select$3 or switch$3) near3 ((transmission or signal) near2 speed))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:30
87	S87	17	((select$3 or switch$3) near3 ((transmission or signal) near2 speed)) near10 ((fault$1 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near3 sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:32
88	S88	16	((select$3 or switch$3) near5 ((transmission or signal) near3 speed)) near10 ((fault$1 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:34
89	S89	2	((select$3 or switch$3) near5 ((transmission or signal) near3 speed)) same ((fault$1 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (motor near3 (speed or rotation))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:35

	Ref #	Hits	Search Text	DBs	Time Stamp
90	S90	0	((select$3 or switch$3) near5 ((transmission or signal) near3 speed)) same ((fault$1 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (motor near3 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:35
91.	S91	0	((select$3 or switch$3) near5 ((transmission or signal) near3 speed)) same ((fault$1 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (motor near5 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:35
92	S92	5	((select$3 or switch$3) near5 ((transmission or signal) near3 speed)) same ((fault$1 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (speed near5 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:36
93	S93	40	((transmission or signal) near3 speed) same ((fault$2 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (speed near5 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:36
94	S94	3	((transmission or signal) near3 speed) same ((fault$2 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (motor near5 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:37
95.	S95	99	((transmission or signal) near3 speed) same ((fault$2 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same (motor near5 (speed or rotation$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:37
96	S96	0	((transmission or signal) near3 speed) same ((fault$2 or error$1 or malfunction$4 or diagno$5 or analy$4 or monitor$3) near5 ((speed or transmission) near3 sensor)) same ((motor near5 transmission) near10 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:38
97	S97	36	((transmission or signal) near3 speed) same ((speed or transmission) near3 sensor) same ((motor near5 transmission) near10 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:39
98	S98	24058	((transmission or signal) near3 speed) near10 motor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:39
99	S99	5616	(transmission near3 speed) near10 motor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:40
100	S100	2131	(transmission near3 speed) near10 (motor near3 speed)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:40
101	S101	334	(transmission near3 speed) near10 ((motor near3 speed) near5 ratio)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/11/18 07:41